# Weathertzstton Assistance Program

# Work Order Bid (ID)

### **WORK ORDER INFORMATION**

Work Order Name: WO/17017UC-0965/1

Work Order Type: Weatherization

Audit Name: 17017UC-0965

### **CLIENT INFORMATION**

Client ID: 17017UC-0965

### **AGENCY INFORMATION**

Agency: Upper Cumberland H R A Agency Phone: (931) 528-1127

Address: 3313 Williams Enterprise Drive Fax:

Cookeville, TN 38506 *Email Address:* 

Agency Contact: Carlisle, Ron Work Phone:
Cell Phone:

Email Address:

Company Name & License Number:	
Contractor's Signature:	

### **COMMENT**

1976 SITE BUILT HOME

## **Measures**

Λ	Measure 1 DWH	l Pipe Insulation			Componen	ts			Inspected	
C	omment									
				Estimated			Actual			
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
1	Insulation	DHW Pipe Insulation	Each	1						
		wrap water pipes								
2	Labor	DHW Pipe Insulation	Each	1						
0	ther Detail									
				Measur	e Sub Total:			Sub Total:		
	Field Notes:						I			
	ricia ricico.									
						_				
		l Tank Insulation			Componen	ts			Inspected	
C	omment									
					Estimated			Actual		
	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
	Hot Water Equipment	DHW Tank Insulation	Each	1						
		R-10 minimum-use bubble wrap								
2	Labor	DHW Tank Insulation	Each	1						
0	ther Detail									
0	ther Detail									
0	ther Detail									
0	other Detail			Measur	e Sub Total:			Sub Total:		
				Measur	e Sub Total:			Sub Total:		
	ther Detail Field Notes:			Measur	e Sub Total:			Sub Total:		
				Measur	e Sub Total:			Sub Total:		

Measure 3 Flo	or Ins. R-19			Componen	ts F1		,	nspecte	
Comment			Estimated			Actual			
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
1 Insulation	Floor Insulation - Fiberglass Batts - R-19	SqFt	1519						
Other Detail									
			Measure	e Sub Total:			Sub Total:		
	ic Ins. R-30			Componen	ts AT1			nspecte	
	ic Ins. R-30			Componen Estimated			I Actual	nspecte	
Comment	ic Ins. R-30  Description / Comment	Units	Qty	•		Qty		Inspecte	
Comment # Material / Labor		<i>Units</i> SqFt		Estimated		Qty	Actual		
Comment # Material / Labor	Description / Comment Attic Insulation - Blown		Qty	Estimated		Qty	Actual		
# Material / Labor  1 Insulation	Description / Comment Attic Insulation - Blown		Qty	Estimated		Qty	Actual		
# Material / Labor  1 Insulation	Description / Comment Attic Insulation - Blown	SqFt	<b>Qty</b> 1891	Estimated			Actual		

Measure 5 Fix Moisture Problems (Basement/Crawlspace) 1256			Components 6 SQ. FT						Inspected	
C	Comment									
				Estimated			Actual			
#	Material / Lak	bor	Description / Comment	Units	Qty	<b>Unit Cost</b>	Total	Qty	Unit Cost	Total
1	Health and S Items	Safety	Moisture Barrier Needed	SqFt	1					
2	Labor		Labor	Hour	1					
C	Other Detail					1		,		
L										L
					Measur	e Sub Total:			Sub Total:	
	Field Notes:									
				Work Or	der Gra	nd Total:		Gran	d Total:	